

**CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD—  
LOS ANGELES REGION**

101 CENTRE PLAZA DRIVE  
MONTEREY PARK, CA 91754-2156  
(213) 266-7500



June 12, 1992

Mr. Chet Young  
Stoody Company  
16425 Gale Ave., P.O. Box 90426  
Industry, CA 91745-0426

**REVIEW OF WORK PLAN FOR ADDITIONAL SUBSURFACE INVESTIGATION NEAR  
THE REMOVED CLARIFIER (FILE NO. 105.0263)**

The following documents prepared by Clayton Environmental Consultants (CEC) were received by this Regional Board:

- A. "First Quarter Groundwater Monitoring Results" dated April 30, 1992.
- B. "Soil Remediation for Clarifier and Sump" dated May 11, 1992 (a revised report).
- C. "Soil Remediation for Clarifier and Sump" dated May 15, 1992 (a revised report superseding the May 11 copy).
- D. "Work Plan for Additional Subsurface Soil Investigation near the Removed Clarifier" dated May 18, 1992.

Two additional copies of Document C must be submitted to this office.

Upon review of Document D, the following comments pertain:


- 1. As agreed in a telephone conversation between Mr. Guy Romine of CEC and Samuel Yu of Board staff, the proposed number of borings and the locations of BH-19 and 20 are acceptable with the understanding that the middle section of the northern edge of the excavation is contaminated (as revealed by confirmation sample CL-6-N) and will be further excavated.
- 2. A minimum of one additional 30-foot boring is required west of the excavation near confirmation samples CL-5-W and CL-8-SW which showed elevated concentration of contaminants.

Mr. Chet Young  
Page 2

3. Soil samples must first be analyzed for volatile organic compounds before subjecting them to total petroleum hydrocarbon analysis.

The work plan is now conditionally approved provided that the above comments are incorporated and an acceptable statement documenting so is received before the commencement of field work. Notify Board staff at least 7 days in advance of any field operation.

Three copies of an investigation report are due to this office by July 20, 1992. Please contact Samuel Yu of our staff at (213)266-7541 if you have any questions, and address all correspondence to his attention.

A handwritten signature in black ink, appearing to read "Hank H. Yacoub", with a stylized flourish at the end.

HANK H. YACOURB  
Supervising Water Resource  
Control Engineer

cc: \ Phillip Ramsey, USEPA, Region IX  
Don Howard, Howard Engineers, Puente Basin Watermaster  
John Maulding, San Gabriel Valley Watermaster  
Guy Romine, Clayton Environmental Consultants